


UNCONTROLLED DOCUMENT

PART NUMBER		REV.
SSF-LXH100M-XXX		Q
REV.	E.C.N. NUMBER AND REVISION COMMENTS	DATE
	SEE PAGE 2.	



NOTES:

- [1] 1. PACKAGE PARTS IN ANTI-STATIC TUBES.
- [2] 2. AN "X" ON TABLE DENOTES NO LED, HOLDER ONLY.

[3] BOM: -AS REQUIRED PER CHART.

SSH-LXH100M, HOLDER.  
 SSL-LX509F3GD LED, GREEN.  
 SSL-LX509F3ID LED, RED.  
 SSL-LX509F3YD LED, YELLOW.  
 SSL-LX509F3GGD LED, GREEN BICOLOR.

- [4] SSL-LX509F3GIW LED, GREEN/RED BICOLOR.
- [5] SSL-LX509F3IGW LED, RED/GREEN BICOLOR.

UNCONTROLLED DOCUMENT

\*UNLESS OTHERWISE SPECIFIED TOLERANCE IS  $\pm 0.25$ mm ( $\pm 0.010$ " )

REV. Q	PART NUMBER SSF-LXH100M-XXX	CONFIDENTIAL INFORMATION THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC, THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.	<b>LUMEX</b> INCORPORATED	290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: 1-847-359-2790 WEB: HTTP://WWW.LUMEX.COM
MATING T-5mm (T-1 3/4) RIGHT ANGLE FAULT INDICATOR, LED COLORS PER CHART.		RELIABILITY NOTE OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.	DRAWN BY: BC	CHECKED BY: APPROVED BY: DATE: 12-16-91 PAGE: 1 OF 2 SCALE: N/A