
UNCONTROLLED DOCUMENT


6.10 [0.240]

Ø5.20 [Ø0.205]

6.75 [0.266]



Γ 0.	.80	[0.031]			
_		A			



(X)



PART NUMBER


SSH-LX5090


E.C.N. NUMBER AND REVISION COMMENTS


E.C.N. #10BRDR. & MODELED.

REV.

DATE 6-11-99










1. MATERIAL: POLYPROPYLENE (PP), BLACK.



UNCONTROLLED DOCUMENT

*UNLESS OTHERWISE SPECIFIED TOLERANCE IS ±0.25mm (±0.010")

REV. PART NUMBER SSH-LX5090

T-5mm PANEL INDICATOR, 2 PC. HOLDER.

CONFIDENTIAL INFORMATION

THE INFORMATION CONTAINED IN THIS DOQUIENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECHFICALLY AUTHORIZED IN WRITING BY LUMEX INC. THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONTIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

LUMEX
INCORPORATED

290 E. HELLEN ROAD PALATINE, ILLINOIS 60067 PHONE: 1-847-359-2790 WEB: HTTP://WWW.LUMEX.COM

DRAWN BY:	CHECKED BY	APPROVED BY	; DATE; 5-13-97
			PAGE: 1 OF 1
-			SCALE: N/A