



DATE

REVISIONS

REV

DRAWING NUMBER
SSL-LX5091XX

REV



RELIABILITY NOTE
 OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE
 THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE
 FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELLEN ROAD
 PALATINE, ILLINOIS 60067
 (847) 359-2790

CONFIDENTIAL INFORMATION
 THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INCORPORATED.
 EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INCORPORATED, THE HOLDER OF
 THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT
 SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

DATE:	DWN:	CHK'D:	APPD:
SCALE: N/A			

T-5mm (T-1 3/4) LED,
 'X' COLOR, 'X' DIFFUSED.

UNLESS OTHERWISE SPECIFIED TOLERANCE IS ±.25mm (±0.010")

PAGE 1 OF 1

DRAWING NUMBER
SSL-LX5091XX

REV