

UNCONTROLLED DOCUMENT

ø23.00	[ø0.906] —
	(((() +))))
	LFD —






PART NUMBER


CIS-RC11A125190Y

REV.	E.C.N. NUMBER AND REVISION COMMENTS	DATE
Α	E.C.N. #11181.	11.02.04
В	E.C.N. #11148.	12.08.06

CHARACTERISTICS				
rating	10A AT 125VAC			
LED COLOR	YELLOW			
CIRCUIT OPERATION	SPST			
NO. OF PINS	4			
SWITCH OPERATION	ON-OFF			



INTERNAL CIRCUIT





REV.

*UNIESS OTHERWISE SPECFED TOLERANCES PER DECIMAL PRECISION ARE: X=±1 (±0.039), XX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD 97ZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). NN= +0.000 NAX.= +0.

PART NUMBER REV. CLS-RC11A125190Y В

YELLOW LED ILLUMINATED, ROUND ROCKER SWITCH, RATED FOR 10A AT 125VAC.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX INC. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUNEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

RELIABILITY NOTE OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com

TW WEB: www.lumex.com.tw

DRAWN BY: JC

CHECKED BY:

APPROVED BY:

DATE: 12.08.06 PAGE: 1 OF 1 SCALE: N/A