www.schurter.com/pg05






Connectors





S


Length

50 mm












KM with shield









Diagrams

Fuseholder 1- or 2- pole



1) Line 2) Load

Derating Curves for Fuseholders





Distributor-Stock-Check | SCHURTER-Stock-Check | e-Store

Variants

Fuse drawer must be ordered separately (see accessories). Fingergrip and Extra Safe. The same drawer as used by type KEA.

Fuseholder	Line Switch	EMC-Shielding	Order Number
1 pole	2-pole	-	KM00.1205.11
2-pole	2-pole	-	KM00.1105.11
1 pole	2-pole	With EMC-shield and without line filter	KM01.1205.11
2-pole	2-pole	With EMC-shield and without line filter	KM01.1105.11

Packaging unit 50 Pcs

Required Accessory

Description

Fusedrawer 2 Fusedrawer with and without voltage selector insert



Fingergrip, 2-pole	4301.1401
Extra-Safe, 2-pole	4301.1403
Fingergrip, 1 pole	4301.1405
Extra-Safe, 1 pole	4301.1407

Accessory



Assorted Covers Rear Cover

Cord retaining kits Cord retainning strain reliefe

Flat head, A

0859.0076

4700.0001

